MULTI-COM.PL



Bootloader repair HTC 7 Mozart T8698

Product ID: 8954

Price: **30.00 EUR**

Product weight: **0.40 kg**

Description:

Bootloader repair HTC 7 Mozart T8698 it's service that allows repair your damaged phones after unsuccessful firmware upgrade/downgrade. Repair are make using our JTAG JIGs so we don't solder in phones (exception are phones that using Molex port connector - then this connector are installed as same as in any authorized service point).

Go to the product

Contact details:
Telefon: +48 17 227 00 25
Infolinia:0 801 671 717
E-mail: biuro@multi-com.pl
Skype: Multi-COM

Adsress:
Multi-COM Sp. z o.o.
ul. Stanisława Krzaklewskiego 31b
36-100 Kolbuszowa
POLSKA

Datasheet valid 2017-07-29 03:00:09